

<b>Effective Date</b>	December 15, 2021
<b>Impacted Manual #(s)/Manual Title(s):</b>	
M-10: Pre-scheduling Operations, Revision 40	
<b>Conforming Order(s):</b>	
Black Start Filing Docket No. ER21-1635-00	
<b>Associated Issue Tracking Title:</b>	N/A
<b>Committee Approval Path - What committee(s) have already seen these changes?</b>	
Planned committee reviews/endorsements:  SOS: October 4, 2021, November 1, 2021 RSCS and TTMS: October 15, 2021 OC: October 7, 2021, November 4, 2021 (Endorsement) MRC: November 17, 2021, December 15, 2021 (Endorsement)	
<b>MRC 1<sup>st</sup> read date:</b>	November 17, 2021
<b>MRC voting date:</b>	December 15, 2021
<b>Impacted Manual sections:</b>	
See detailed list below	
<b>Reason for change:</b>	
<p><b>Periodic Cover to Cover Review</b></p> <p><b>Section 2.1 Generation Outage Reporting Overview</b></p> <ul style="list-style-type: none"> <li>Clarified eDART ticket requirements for units that do not have a day-ahead must offer requirement</li> <li>Corrected use of eDART Reportable MW</li> </ul> <p><b>Section 2.2 Planned Outages</b></p> <ul style="list-style-type: none"> <li>Clarified the language defining the Peak Period Maintenance Season</li> </ul> <p><b>Section 2.2.4 Planned Outage Restrictions for Black Start Units</b></p> <ul style="list-style-type: none"> <li>Moved to new Section 2.5.1 Outage Restrictions for Black Start Units</li> </ul> <p><b>Section 2.3 Maintenance Outages</b></p> <ul style="list-style-type: none"> <li>Clarified the language defining the Peak Period Maintenance Season</li> </ul> <p><b>Section 2.3.1 Maintenance Outage General Information</b></p>	

- Removed examples and clarified language when a generation resource fails prior to the scheduled start time of an outage.

**Section 2.5.1 Outage Restrictions for Black Start Units**

- Moved from Section 2.2.4 and expanded to include both Planned Outages and Maintenance Outages in accordance with updated OATT language.
- Clarified Black Start Unit substitution rules.

**Section 2.5.2 Outage Reporting for Cranking Diesels and Auxiliary Equipment**

- Moved existing manual language to new section under Section 2.5 Outage Reporting for Facilities Providing PJM Black Start Service