

## **Executive Summary Manual Changes**

Effective Date	6/15/2021	
Impacted Manual #(s)/Manual Title(s):		
PJM Manual 36: System Restoration		
Conforming Order(s):		
Associated Issue Tracking Title:		
Committee Approval Path - What committee(s) have already seen these changes?		
First Reads:		
MRC 1st read date:	4/21/2021	
MRC voting date:	5/26/2021	
Impacted Manual sections:		
Attachments B, F, G, and H		
Reason for change:		
Annual update requirement.		
Summary of the changes:		
Annual Update Cover to cover review.		
Attachment B Exhibit 16: Replaced with a clearer image		

 Attachment G: Updated Table 1, Annual Restoration Plan Review Deadlines, with current list of Transmission Owners.

Attachment F: Removed information; Linden and Neptune restoration plans are in eDART.



## Executive Summary Manual Changes

•	Attachment H: Updated Under Frequency Load Shed table with new data and noted PJM's
	UFLS program does not require automatic switching of capacitor banks, transmission lines, or
	reactors (PRC-006 R10).